Boston Daily Globe; Apr 28, 1887; ProQuest Historical Newspapers Boston Globe (1872 - 1927)

MANY DEFECTS

Found in the Ill-Starred Bussey Bridge.

Bad in Contract and Bad in Make,

Bad in Testing and Very Bad in General.

So Say the Commissioners Who Heard the Evidence.

Sensible Suggestions About the Care of Railroads.

Severely Censured. Several Faults Which Have Been

Known for Years.

Engineer White and Mr. Howins Both

Yesterday afternoon the report of the Yesterday aftornoon the report of the railroad commissioners regarding the Roslindale disaster on the Boston & Providence railroad was presented to the Senate.

After reviewing the history of the accident and also of the road at length, Ane commissioners make the following argument:

dent and also of the road at length, Ane commissioners make the following argument:

It appeared that A. A. Folsom, the superintendeut of the road, and the superintendeut of the road, and the superintendeut of construction. George F. Folsom, knew that the bridge was being built partly at the Trenton Iron and Steel Company's works and partly at the Phemix Bridge Company's works, and the standing or even the existence of the Metropolitan Bridge Company, and knew only and looked only to Mr. Hewins for responsibility in the matter. They had known him previously as engineer for the Moselev Iron Works at Readville, and his bearing impressed them as that of an able and urright man. A. A. Folsom, the superintendent of the road, also tastified that he made inquiry of one man, now lead, in regard to Mr. Howins, and received a favorable report, and thinks may have inquired of one or two others.

The main tension members of the bridge were made at the Phemix Iron Works, and were of excellent workmanship and apparently of good material. The rost of the bridge was made at the Trenton Iron and Steel Company; but it appeared that the work there was done, not under the superintendence of the officers of that company; but it appeared that the work there was done, not under the superintendence of the officers of that company, but under the superintendence of the officers of that company furnishing only the Iron, the company furnishing only the Iron, the company furnishing only the Iron, the company furnishing the toom the superintendence of the construction and repairs of buildings and of bridges, that for ten years previous to that date he had worked as a machinist in the shops of the company, that is first experience in bridge building was in connection with these trusses in the Bussey bridge, that he was at the bridge but little while the construction was going on, that

He Mad Other Business

to attend to, and that he trusted wholly to Mr. Hewins to build the bridge properly and put it up in proper shape.

It further appears that the railroad company employed no expert to pass either upon the original design of the bridge, or upon the bridge after it was constructed, and, in fact, consulted nobody in regard to it.

and, in fact, consulted nobody in regard to it.

If the management of the railroad had taken the trouble to make inquiry, it would have learned that the company which Mr. Hewins professed to represent did not in fact exist, and that not only the design but the quality of much of the materials and workmanship of the bridge depended solely upon his ability, honesty and faithfulness. As a matter of fact, the material and workmanship of the compression members appear to have been sufficiently good. The design in many of its details proved to be bad.

appear to have been sufficiently good. The design in many of its details proved to be bad.

Such a way of doing business would be lax in a purely commercial transaction. In contracting for and constructing a bridge, in dealing with a matter involving the salety of life, it was culpable.

Walter E. White, the engineer, testified that he had about ninety rounds of steam and worked steam with the throttle open two or three notches all the time after leaving Roslindale, but that he had not, in his oninion, accuired a sneed of about more than lifteen miles an hour because the air brakes came off slowly and retarded the train. The condition of the wreck indicated that the train must have been going considerably faster than the engineer supposed. The experts generally placed the rate at thirty miles an hour or more.

The engineer had served in that capacity on the Dedham branch for more than thirty years. He knew that the rules limited the speed on the old bridge to twelve miles an hour, and

Thought that the Same Rule

applied to the new bridge. The superintendent of the road subsequently testified

applied to the new bridge. The superintendent of the road subsequently testified that the limitation as to speed had been removed after the bridge was rebuilt in 1876 and he submitted a printed copy of the present "rules and regulations," the second and last edition of which was issued in 1881. It often happens that an employe of long standing blindly follows routine and loses sight of the reason or authority which established the practice. This may be a source of danger, and should be guarded against. The engineer showed that he was a man who would tell what he believed to be the truth, no matter how disastrous the consequences might he to himself.

The theory that the disaster was due to a derailment of the train received no sufficient confirmation. On the contrary, the evidence that neither the ties on the embankment south of the bridge itself showed any slips of derailment. If a derailment of the Hewins trues.

A theory was also started at the investigation that the disaster might have been daused by the dropping of a brake beam between the ties, but the theory was not supported by the necessary evidence. If a brake beam dropped at all it must have dropped within a few feet of the long true is the twenty-nine feet a second; of them the substant have dropped within a few feet of the hangers.

A speed of fitten miles an hour sequivalent to about twe-nty-time feet a second; of theirty miles an hour, to about tventy-nine feet a second. A cannon bull falls sixteen feet the first second. The length of a car is about fifty feet.

Warnings to the Read.

Warnings to the Road.

The evidence shows that there has been

The evidence shows that there has been considerable anxiety on the part of passengers in regard to the safety of this bridge, and in various ways and at various times this anxiety has been prought to the attention of the management of the foad. Though in some cases this anxiety was caused by the discovery of loose nuts on the Parker trus, it was generally a vague fear, founded on no known defect in the bridge, but apparently largely due to the skew of the bridge and to the fact that the track on both sides of the bridge ran on high embankments.

but apparently largely due to the skew of the bridge and to the fact that the track on both sides of the bridge ran on high embankments.

In December, 1881, the Board of Railroad Commissioners wrote to the superintendent of the Boston & Providence railroad in relation to this bridge.

It appeared in evidence that shortly after the receipt of this letter a test of the bridge was made, but no record of such test was returned to the board, nor was the test followed by a sories of tests, which the letter of the board indicated was necessary in order to show conclusively whether the bridge was maintaining its strength.

It appeared that examinations of the bridge was maintaining its strength. The progress of the strength of the bridge had been made every spring and fail by George F. Folsom, the superintendent of construction, and he described fuily his method of going through the bridge and examining its details. He testified that he

had detected no fault in the construction of the bridge, except that it would be better if made of fewer pieces; that he never had any anxiety about any portion of the bridge that was covered up; that he did not know how the floor-beams under the joint-blocks at the ends of the trass were supported, but supposed that they were supported, but supposed that they were supported on iron stirrup straps, which he thought were one and a half-inch square; that he could not examino these stirrip straps, and never thought they were an important feature of the bridge until he saw them lying on the ground.

Buch was the examination made by the superintendent of construction to ensure the safety of passengers riding over that bridge.

The hangers held up the floor beams. When the floor beams fell the floor system would fall, and yet it never occurred to the man who was supposed to have superintended the construction of the bridge, and to whom was entrusted the examination of the bridge every spring and fall, it never occurred to him that the strongth and condition of these hangers was vital, and should have been an important feature in his examination. Moreover, he did not know how the hangers were made, his supposition in regard to their shape and size was incorrect, and he did not have, nor did the road have, any drawings showing their construction and dimensions.

It is a defect in any bridge if a vital part, no matter what excess of strength it may have, is unnecessarily covered so that it cannot be inspected. In this bridge not only was a vital part unneces-arily covered, but no one in the employment of the corporation knew anything about its construc-

cannot be inspected. In this bridge not only was a vital part unnoces-arily covered, but no one in the employment of the corporation knew anything about its construction or its strength, and, as a matter of fact, It Was So Constructed

as to be sure to weaken under continued use

and was insufficient to do its work with safety, even had it been so placed as to be subject to full and constant inspection

subject to full and constant inspection.

Mr. George F. Folsom, being unable by reason of sickness to answer certain questions of the board in regard to the consruction of the floor system, communicated information relating thereto to A. A. Folsom, the superintendent, in the following letter, which was submitted to the board:

which was submitted to the board:

BORTON, March 29, 1887.

A. A. Folsom, Esq.

DEAR SIK—The ties on the liussey bridge all extended eighteen inches outside of rail on east side, and were all eighteen inches on centres.

The short ties that butted against truss were seven feet five inches long; the ties at both ends of the bridge were ton feet long.

The other were six by ten and eight inches apart. Guard plank outside each rail ten inches wide and three inches thick covered bridge and abutments. Yours truly,

It will be seen from this letter that the

The ties were six by the and eight then inches wide and three luches thick covered bridge and abutments. Yours truly.

It will be seen from this letter that the superintendent of construction states that the superintendent of construction states that the spaces between ties on this Bussey bridge were eight nuches. Mr. E. S. Philbrick, the expert emp oyed by the road, and Mr. Thomas Doane, the expert employed by the commissions who took measurements of the ties and the spaces between them as they were found at the wrock, testify that the spaces between the ties on this bridge were from fifteen to eignteen inches, instead of eight inches as tated in the letter of the superintendent of construction.

In spite, then, of the circular of 1881, and of the letter of 1882, each of which called the attention of the superintendent of the Boston & Providence railicad to the importance of having ties on bridges laid closely together, the ties on this bridge romained unchanged, and at the time of the accident were so far apart that had a train been derailed upon that bridge, the destruction of the bridge would have been inevitable; the spaces between the ties were so great that the wheels would have sunk down between them, and the bridge would have been wrenched and torn to pieces. Moreover, if a brake beam had fallon, it would, in all probability, have caught between the sunerintendent of construction would deny that the spaces between the ties on this bridge were too great. As it happened, the accident was not caused by the delects of the les seens trade to its iong-continued neglect to remove this undoubted

Element of Panger.

The contract for rebuilding the bridge in Element of Danger. The contract for rebuilding the bridge in

The contract for rebuilding the bridge in 1876 was made without proper examination as to the standing of the contractor. Those who acted for the corporation in making the contract had not sufficient knowledge of iron bridge building to enable them to pass intelligently upon the design and specifications.

The design and specifications for the bridge were not such as should have been accented.

The bridge was constructed practically without superintendence on the part of the corporation, and the corporation neglected to preserve a copy of the specifications, drawings and strain sheets.

The tests of the bridge were not made in the presence of any one acting for the corporation. Broom the time of the construction of the walle.

ration who was qualified to judge of their value.

From the time of the construction of the bridge to the day when it fell the railroad com any had caused it to be examined by one man only, who, year after year, passed over y tal parts of the bridge without realizing that they were of importance. This man had been in in the employment of the corporation for a long series of years, his trade was that of a machinist, he had not been educated as a dvil engineer, and the management had abundant reason to know that he was not qualified, and had had no opportunity to qualify himself to do the work assigned to him with reference to this bridge.

mended by the board in 1881 was not made. In the erection and inspection of bridges the management of a railroad is bound to

made.

In the crection and inspection of bridges the management of a railroad is bound to Exercise the Utinest Care.

Had such care been exercised there is every reason to believe that the disaster would have been prevented. On the thirty-second page of the last report of the commission is the following: "The board renews the expression of its belief that a preventible accident is a crime."

Notwithstanding the repeated warnings of the board the spaces between the ties on this bridge were far too great for salety.

Notwithstanding the recommendation of the board in 1881, no suitable guard rails or guaid timbers were placed upon the bridge.

The Westinghouse automatic air brake, a salety appliance, remarkable alike for its simplicity and electiveness, and long ago approved and adopted by all loading railroads, was not in practical operation on this train, noither was the train funished with a sufficient number of brakemen to comply with the requirements of the statute.

The disaster and the facts which have been disclosed impose a grave responsibility on the board of directors. It is their duty, by the most searching inquiry, to ascertain forthwith whother any other work has been done in a like negligent and incompetent manner, whether in other matters reasonable and well-proved piecautions against accident have been ignored or neglected, and whether false economy has been practised and safety sacrliced. They should not rest until they have taken the most energetic measures, without regard to exceed and safety sacrliced. They should not rest until they have taken the most energetic measures, without regard to exceed and safety sacrliced. They should not rest until they have taken the most energetic measures, without regard to exceed and safets conomy has been practised and safety sacrliced. They should not rest until they have taken the most energetic measures, without regard to exceed and safets conomy has been practised and the censure better and safer management in the future. So far as relates to bridges the

Fortunately there are but few bridges on the line. In integration of the sentence of condemnation called for by the forecoing findings and in support of the hope that the history of the Bussey bridge is exceptional, it must be remembered that from 18.00, when the Board of Ralfroad Commissioners was created, up to the time of this disaster, a period of eighteen years, there has been no train accident on the Boston & Providence railroad which resulted in the loss of a life of, or even in serious injury to a passonger.

a life of, or even in serious injury to a passonger.

The accident furnishes another proof of the necessity of avolishing the deadly car stove.

As pridges embody many possibilities of danger, it is proper that

Special Means Should He Taken secure careful, competent and faithful

Special Means Should Re Taken
to secure careful, competent and faithful
construction, and a thorough and scientific
examination of them by the railroads at regular intervals, followed
by a thorough State inspection. The
importance of such action is emphasized by the fact that the weight of engines and of the rolling stock of railroads
and of the loads carried has been increasing
for many years. The weight of engines and
rolling stock has doubled within twenty
years. Moreover, the speed of the heavy
passenger express and through freight
thains has also largely increased.

The examination made by the Board of
Commissioners can at best be but cursory.
There are over a thousand bridges in the
State, and no member of the board, no matter which is scientific education may be,
can, in addition to his other duties as commissioner, make anything but a brief, partial and unsatisfactory examination of
them. A proper inspection in bohalf of the
State would require practically the whole
time of a bridge expert.

The board recommend the passage of an
act requiring every railroad, at least once
in two years, to have a thorough examinatien of all-bridges on its lines made by a
competent and experienced civil engineer,
who shall report in writing to the coporation and to the Board of Railroad Commissioners the results of his examination, his conclusions and recommendations. The reports should embrace
such information in relation to the
history and construction of each bridge, including det il diawings and strain sheets,
as may be called for by the Board of Railroad Commissioners, and said board should
be authorized to employ a competent expert to examine such reports and unskes
such further examination of the bridge
structures as may be deemed necassary or
expedient.

Edward W. Kinsley,
Evenett A. Stevens.