

BOSTON FIRE DEPARTMENT  
FIRE REPORT, ENGINE 20



REPORTED TO

Dep. Chief Stickel

ORDERED TO QUARTERS BY

same

Alarm BO41521-5<sup>th</sup> alarm.  
Time 11.02 P.M.  
Location 17 Piedmont St.  
Boston Nov. 28, 1942

Reached fire in see remarks minutes

There was no delay caused by

Absent from quarters see remarks hours. On duty at fire 2 hours 34 min.

Hydrant at High Pressure #547 in good condition

Hydrant pressure 120 lbs. Engine pressure — lbs. Feet of hose used 500' 2 1/2'

Extinguishers used \_\_\_\_\_ Detailed at fire \_\_\_\_\_

PASSED WATER		WHERE	UNDER ORDERS OF
hours, <u>2</u> min.		<u>1<sup>st</sup> floor</u>	<u>Dep. Stickel</u>
"	"	<u>" overhauling</u>	<u>" Kenney</u>
"	"	<u>" removing</u>	<u>D.C. Robertson</u>
"	"	<u>bodies.</u>	
"	"		
"	"		
"	"		

REMARKS

Company covered Eng. 43 on 3<sup>rd</sup> & Eng. 7 on 4<sup>th</sup> & responded to fire on 5<sup>th</sup> alarm. Returned to Eng. 7 from fire & was sent to own qtrs by F.A. Office on reporting from Eng. 7. Absent from own quarters 3 hrs. 32 minutes. M. O. Crawford Sgd. 27 pres. Stickel

Edwin F. Fay Capt.