



BOSTON FIRE DEPARTMENT FIRE REPORT, ENGINE *Rescue # 3*

REPORTED TO

Deputy Chief Steibel

ORDERED TO QUARTERS BY

Chief of Dept. Pope

Reached fire in *about 4* minutes

Alarm *Ordered to Box 1521 by F.H.*

Time *10.26 P.M.*

Location *17 Piedmont St*

Boston *Saturday Nov. 28, 1942*

There was *No* delay caused by

Absent from quarters *3* hours *11* min. On duty at fire *3* hours *2* min.

Hydrant at _____ in _____ condition

Hydrant pressure _____ lbs. Engine pressure _____ lbs. Feet of hose used _____

Extinguishers used _____ Detailed at fire _____

PASSED WATER		WHERE	UNDER ORDERS OF
hours,	min.		
"	"		
"	"		
"	"		
"	"		
"	"		
"	"		
"	"		

REMARKS

Assisted in getting people out of cellar through the Winchester St. exits.
Assisted in getting victims out of street floor through the Winchester St. exits.
St. Martin present detail from Eng #6
Advanced line in cellar.
John J. Martini
Lieutenant